


**Figure 2 (online suppl.) Sample ECG trace with and without Artefact**



Screenshot of the ECG trace of the ICON non-invasive cardiac output monitor (Osypka Medical, Berlin, Germany) A: with artefact, Signal Quality 30% B: after uncoupling from energy supply Signal Quality 100%